


T4S + 1

Put some shrink wrap around the leads of the cap to avoid shorts.



you may try caps between .005 and .02 µf. the smaller the cap the sweeter the sound in Pos 4

Connect to ground!!

- Pos 1. NECK Pn.
- 2. NECK + Bridge Pn.
- 3. Bridge Pn
- 4. NECK + Bridge Pn. 1/2 out of Phase
- 5. NECK Pn with 10% low low end.

BL